C-3 Report on Intensity Values - continued

The purpose of this section is to show a graphic of lidar data points colored by intensity. Blank flight lines can indicate a collection or processing problem dealing with lidar intensity attribute information.

Data Source - D:\00_Cherry\Client_Swaths
Result Path - D:\00_Cherry\Cherry_QC\C_3\ColorByIntensity.jpg