C-3 Report on Intensity Values - continued

The purpose of this section is to show a graphic of lidar data points colored by intensity. Blank flight lines can indicate a collection or processing problem dealing with lidar intensity attribute information.

Data Source - Z:\MARS_QC\2900112_Lot_7\Generated_Swath
Result Path - Z:\MARS_QC\2900112_Lot_7\Output\C_3\ColorByIntensity.jpg