DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity

The purpose of this section is to show a table of LAS 1.4 file integrity test results for each tiled file.

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
2000 2000		2000	DAGC	DACC	DAGG		2400
2990_9310.las	0	PASS PASS	PASS	PASS	PASS	0	PASS
2990_9400.las 2990_9415.las	0	PASS	PASS PASS	PASS PASS	PASS PASS	0	PASS PASS
3005_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3005_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9580.las	0	PASS	PASS	PASS	PASS	0	PASS
3020_9595.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9250.las 3035_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9280.ias 3035_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9310.las 3035_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
JUJJ_7J2J.Id3	· ·	rmoo .	rmaa	FMOO	FM33	U	rnoo

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3035_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9520.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9535.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9550.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9565.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9580.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9595.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9610.las	0	PASS	PASS	PASS	PASS	0	PASS
3035_9625.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9490.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9505.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9520.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9535.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9550.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9565.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9580.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9595.las	0	PASS	PASS	PASS	PASS	0	PASS
3050_9610.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

Mysical Control 1 Mysical Control Section 1 0 1	File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
SMACHEMENT 1 May Wilden May Wilden May Wilden May Ma	3050_9625_las	0	PASS	PASS	PASS	PASS	0	PASS
5000 1000 <th< td=""><th></th><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>								
Month 1 150 <th></th> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0</td> <td></td>							0	
Mathematical State of the Company of Mathematical State of St		0					0	
Part Wilson		0					0	
Mathematical State of Sta		0					0	
1548-1754 15 162 16		0	PASS	PASS	PASS	PASS	0	PASS
Act of March Act of March March <th></th> <td>0</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>0</td> <td>PASS</td>		0	PASS	PASS	PASS	PASS	0	PASS
Absolution Comment Management	3065_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
546, 750 Mag 61 610 Mag 800 Mag 800 Mag 61 Mag 62	3065_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
Section of Control of	3065_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
144 145	3065_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
504, Davids 100 <th< td=""><th>3065_9250.las</th><td>0</td><td>PASS</td><td>PASS</td><td>PASS</td><td>PASS</td><td>0</td><td>PASS</td></th<>	3065_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
25. Mysiland95.95.95.95.95.95.17. Williand95.95.95.95.95.18. Williand95.95.95.95.95.95.18. Williand95.95.95.95.95.95.18. Williand95.95.95.95.95.95.18	3065_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
Modern M	3065_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
50-50-1901 10 100 1	3065_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
100, 100	3065_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
504, Spring 10 Mod	3065_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
PARE PATRICULATION PASC PASC <th>3065_9340.las</th> <td>0</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>0</td> <td>PASS</td>	3065_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
DNA DNA PART DNA DNA </td <th>3065_9355.las</th> <td>0</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>0</td> <td>PASS</td>	3065_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
PAGE	3065_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3065_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3065_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3065_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
6016_4440.14 601 685 <t< td=""><th>3065_9430.las</th><td>0</td><td>PASS</td><td>PASS</td><td>PASS</td><td>PASS</td><td>0</td><td>PASS</td></t<>	3065_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
1965, 4973 is 1965	3065_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3065_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS		0		PASS			0	
96, 9650 ka 9455		0					0	
905. \$935. lies 306. \$950. lie		0					-	
968, 9850 land 968, 9850 land 968, 9850 9850 9850 9850 9850 9850 9850 9850		0					0	
306.5_96.5 las 0 PASS		0					0	
966_969.0as 0 PASS PASS PASS PASS PASS PASS PASS PA		0					0	
965.995.liss 0 9ASS PASS PASS PASS PASS PASS PASS 0 9ASS 0		-						
3065_9410.las 0 PASS		0						
3065_9625 las 0 PASS		0						
3065_9640.las 9ASS PASS		0					-	
3065_965.1as 0 PASS		0					-	
3065_9670.las 0 PASS		0					-	
3065_9685.las 0 PASS		0					-	
3080_9100.las 0 PASS		0					-	
3080_9115.las 0 PASS		0						
3080_9130.las 0 PASS PASS PASS 0 PASS 3080_9145.las 0 PASS PASS PASS PASS PASS 3080_9160.las 0 PASS PASS PASS PASS PASS		0					-	
3080_9145.las 0 PASS PASS PASS 0 PASS 3080_9160.las 0 PASS PASS PASS PASS PASS PASS		0					-	
3080_9160.las 0 PASS PASS PASS DASS DASS DASS DASS DASS		0					-	
		0					0	
		0						
3080_9190.las 0 PASS PASS PASS 0 PASS PASS 0 PASS	3080_9190.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3080_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9490.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9505.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9520.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9535.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9550.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9565.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9580.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9595.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9610.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9625.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9640.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9655.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9670.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9685.las	0	PASS	PASS	PASS	PASS	0	PASS
3080_9700.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3095_9310.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data Offs	fset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3095_9325.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9340.las	0	PASS PAS		PASS	PASS	0	PASS
3095_9355.las	0	PASS PAS		PASS	PASS	0	PASS
3095_9370.las	0	PASS PAS		PASS	PASS	0	PASS
3095_9385.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9400.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9415.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9430.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9445.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9460.las	0	PASS PAS	iss I	PASS	PASS	0	PASS
3095_9475.las	0	PASS PAS	iss I	PASS	PASS	0	PASS
3095_9490.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3095_9505.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3095_9520.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3095_9535.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9550.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9565.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9580.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3095_9595.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3095_9610.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3095_9625.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3095_9640.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9655.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3095_9670.las	0	PASS PAS	SS	PASS	PASS	0	PASS
3095_9685.las	0	PASS PAS	SS	PASS	PASS	0	PASS
3095_9700.las	0	PASS PAS	iss I	PASS	PASS	0	PASS
3110_9115.las	0	PASS PAS	iss I	PASS	PASS	0	PASS
3110_9130.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9145.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9160.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9175.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9190.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9205.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9220.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9235.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9250.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9265.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9280.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9295.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9310.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9325.las	0	PASS PAS	SS I	PASS	PASS	0	PASS
3110_9340.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3110_9355.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3110_9370.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3110_9385.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3110_9400.las	0	PASS PAS		PASS	PASS	0	PASS
3110_9415.las	0	PASS PAS		PASS	PASS	0	PASS
3110_9430.las	0	PASS PAS	.SS I	PASS	PASS	0	PASS
3110_9445.las	0	PASS PAS	SS I	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3110_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9490.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9505.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9520.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9535.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9550.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9565.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9580.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9595.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9610.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9625.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9640.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9655.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9670.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9685.las	0	PASS	PASS	PASS	PASS	0	PASS
3110_9700.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9490.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9505.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9520.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9535.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9550.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9565.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9580.las	0	PASS	PASS	PASS	PASS	0	PASS
3125_9595.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3125_9610.las	0	PASS PASS	PASS	PASS	0	PASS
3125_9625.las	0	PASS PASS	PASS	PASS	0	PASS
3125_9640.las	0	PASS PASS	PASS	PASS	0	PASS
3125_9655.las	0	PASS PASS	PASS	PASS	0	PASS
3125_9670.las	0	PASS PASS	PASS	PASS	0	PASS
3125_9685.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9130.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9145.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9160.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9175.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9190.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9205.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9220.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9235.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9250.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9265.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9280.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9295.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9310.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9325.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9340.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9355.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9370.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9385.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9400.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9415.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9430.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9445.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9460.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9475.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9490.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9505.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9520.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9535.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9550.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9565.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9580.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9595.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9610.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9625.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9640.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9655.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9670.las	0	PASS PASS	PASS	PASS	0	PASS
3140_9685.las	0	PASS PASS	PASS	PASS	0	PASS
3155_9115.las	0	PASS PASS	PASS	PASS	0	PASS
3155_9130.las	0	PASS PASS	PASS	PASS	0	PASS
3155_9145.las	0	PASS PASS	PASS	PASS	0	PASS
3155_9160.las	0	PASS PASS	PASS	PASS	0	PASS
3155_9175.las	0	PASS PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3155_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9490.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9505.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9520.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9535.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9550.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9565.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9580.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9595.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9610.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9625.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9640.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9655.las	0	PASS	PASS	PASS	PASS	0	PASS
3155_9670.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9235.las	0	PASS PASS	PASS	PASS PASS	PASS	0	PASS PASS
3170_9250.las	0	PASS	PASS	PASS		0	PASS
3170_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9280.las 3170_9295.las	0	PASS	PASS PASS	PASS	PASS	0	PASS
3170_9245.las 3170_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9310.las 3170_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3170_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
	-					-	

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data Offset To	EVLR Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3170_9355.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9370.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9385.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9400.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9415.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9430.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9445.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9460.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9475.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9490.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9505.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9520.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9535.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9550.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9565.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9580.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9595.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9610.las	0	PASS PASS	PASS	PASS	0	PASS
3170_9625.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9145.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9160.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9175.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9190.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9205.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9220.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9235.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9250.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9265.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9280.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9295.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9310.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9325.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9340.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9355.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9370.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9385.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9400.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9415.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9430.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9445.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9460.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9475.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9490.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9505.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9520.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9550.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9565.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9580.las	0	PASS PASS	PASS	PASS	0	PASS
3185_9595.las	0	PASS PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data Offset To E	VLR Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3185_9610.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9130.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9145.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9160.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9175.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9190.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9205.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9220.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9235.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9250.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9265.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9280.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9295.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9310.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9325.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9340.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9355.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9370.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9385.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9400.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9415.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9430.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9445.las	0	PASS PASS	PASS	PASS	0	PASS
3200_9460.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9055.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9070.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9085.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9130.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9145.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9160.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9175.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9190.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9205.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9220.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9235.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9250.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9265.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9280.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9295.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9310.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9325.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9340.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9355.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9370.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9385.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9400.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9415.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9430.las	0	PASS PASS	PASS	PASS	0	PASS
3215_9445.las	0	PASS PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

100	File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
AMASTOR 1 Male 15 Male 0	2015 04/0 les		DACC	DACC	DACC	DACC	0	DACC
Josephila								
Month		-						
SMARTAN PARTAN								
Septimination 10 100 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>								
MAX-PRING Common Principle								
100								
1968年 日本		-						
1244-1754 124 125 126 1		-						
DAX. MINISTAND SECTION MINISTAND								
NATIONAL PARTITION OF THE PARTITION OF T								
252-2006-16-10-10-10-10-10-10-10-10-10-10-10-10-10-								
INSECURATION C FASS PASS								
1922, 1922		-						
IXI. Qualitation 193		-						
May be discomposed to the control of the control o								
Miss								
Page								
100 100								
50% 10% <td></td> <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>		-						
SAME, MASHAM GROBE PROSE		-						
279.5788k 10 485 10% 1								
Page								
5000 1000 <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>								
1923 1925								
1905 1905		0						
1		0					0	
2320_MacClark 0 PASS		0					0	
1456, 1465 in 1465		0	PASS	PASS	PASS	PASS	0	PASS
945, 9070 last		0	PASS		PASS	PASS	0	
9.1 PASS PASS PASS PASS PASS PASS PASS PAS		0	PASS				0	
4246_9115.lins 0 PASS		0	PASS				0	
24245_1710.las 0 PASS	3245_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
2445_9145.las 0 PASS	3245_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
2445_9160 las 0 PASS	3245_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
2424_9175.las 0 PASS	3245_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
2345_9190 las 9ASS PASS PASS </td <td>3245_9160.las</td> <td>0</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>0</td> <td>PASS</td>	3245_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9206 las 9ASS PASS	3245_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9220 las 0 PASS	3245_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9235.las 0 PASS	3245_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9250.las 0 PASS	3245_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9265.las 0 PASS	3245_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9280.las 0 PASS	3245_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9295.las 0 PASS PASS PASS PASS 3245_9310.las 0 PASS PASS PASS PASS 3245_9325.las 0 PASS PASS PASS PASS PASS	3245_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9310.las 0 PASS PASS PASS 0 PASS 3245_9325.las 0 PASS PASS PASS PASS PASS PASS PASS PASS	3245_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9325.las 0 PASS PASS PASS 0 PASS PASS	3245_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
	3245_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9340.las 0 PASS PASS PASS 0 PASS PASS 0 PASS	3245_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
	3245_9340.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3245_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3245_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9055.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9070.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9085.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3260_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_9085.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_9100.las	0	PASS PASS	PASS	PASS PASS	PASS	0	PASS PASS
3275_9115.las 3275_9130.las	0	PASS	PASS PASS	PASS	PASS	0	PASS
	0	PASS	PASS	PASS	PASS	0	PASS
3275_9145.las 3275_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_9170.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_917.5.lds 3275_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_9190.las 3275_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3275_9250.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

100	File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
Add Pair	3275, 9265 las	0	PASS	PASS	PASS	PASS	0	PASS
Marie Mari								
Motivation10Motivation1							0	
PSAMENTAL IR WIND RES MIN M		0					0	
ASS PARISH PS		0					0	
中の		0					0	
125 Young 126 Young <t< td=""><th></th><td>0</td><td>PASS</td><td>PASS</td><td>PASS</td><td>PASS</td><td>0</td><td>PASS</td></t<>		0	PASS	PASS	PASS	PASS	0	PASS
Fig. 1988 and 1988 an		0	PASS	PASS	PASS	PASS	0	PASS
DST PATE NAME	3275_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
174 Markot 18	3275_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
Distriction Distriction Mode Mode Mode Gene Page Page <th>3275_9415.las</th> <td>0</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>PASS</td> <td>0</td> <td>PASS</td>	3275_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
Act years Description	3275_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
1985 1985	3275_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
Control <t< td=""><th>3275_9460.las</th><td>0</td><td>PASS</td><td>PASS</td><td>PASS</td><td>PASS</td><td>0</td><td>PASS</td></t<>	3275_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
1940-11-14-11-14-11-14-11-14-11-14-14-14-14-	3275_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
Part	3290_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
15. In Fire Control15. In Fire Co	3290_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
Part	3290_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
Heat from the field of the fiel	3290_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3290_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
1987, 1978, 1988 1988 1985	3290_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3290_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3290_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3290_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
PASS	3290_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
PASC	3290_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
980 985 985 985 985 985 985 985 985 985 985	3290_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
1940, 9310, lash 1940, 9310,		0					0	
2900_0225.bbs 0 PASS		0					0	
1988, 1985		0					0	
970		0					0	
12900_0370.las 0 PASS		0					0	
9200_9385.las		0					0	
290,0400 las 0 PASS		-						
290_0415 las 0 PASS		0					0	
3790_49430.las 0 PASS		0					0	
3290_9446.las 9ASS PASS PASS </td <th></th> <td>0</td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td>		0					-	
3290_9460.las 0 PASS		0					-	
3290_9475.las 0 PASS		0					-	
3305_9100.las 0 PASS		0					-	
3305_9115.las 0 PASS		0						
3305_9130.las 0 PASS		0						
3305_9145.las 0 PASS		0					-	
3305_9160.las 0 PASS		0					-	
3305_9175.las 0 PASS PASS PASS PASS PASS PASS PASS PA		0					-	
3305_9190.las 0 PASS PASS PASS 0 PASS PASS PASS		0					-	
		0						
		0						

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3305_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3305_9475.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9415.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9430.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9445.las	0	PASS	PASS	PASS	PASS	0	PASS
3320_9460.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9085.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9115.las	U	PASS	PASS	PASS	PASS	0	PASS
3335_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9160.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3335_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9370.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9385.las	0	PASS	PASS	PASS	PASS	0	PASS
3335_9400.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9085.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3350_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9085.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3365_9280.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3365_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
		PASS				0	
3365_9310.las 3365_9325.las	0	PASS	PASS	PASS PASS	PASS	0	PASS PASS
3365_9340.las	0	PASS	PASS PASS	PASS	PASS	0	PASS
3380_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3380_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9100.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9235.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9280.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9295.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9310.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9325.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9340.las	0	PASS	PASS	PASS	PASS	0	PASS
3395_9355.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9115.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9130.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9145.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9190.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9205.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9220.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9235.las	0	PASS	PASS	PASS	PASS	0	PASS

DPH-1.2 Report on ASPRS LAS File Format (Tiled Data) - File Integrity - continued

File	Number of Points Outside Extent	Offset To Point Data	Offset To EVLR	Number Of Points	Number of Points by Return	Number of Duplicate Points	Return Counts in LAS Header
3410_9250.las	0	PASS	PASS	PASS	PASS	0	PASS
3410_9265.las	0	PASS	PASS	PASS	PASS	0	PASS
3425_9160.las	0	PASS	PASS	PASS	PASS	0	PASS
3425_9175.las	0	PASS	PASS	PASS	PASS	0	PASS
3425_9235.las	0	PASS	PASS	PASS	PASS	0	PASS