

## *C-3 Report on Intensity Values - continued*

The purpose of this section is to show a graphic of lidar data points colored by intensity. Blank flight lines can indicate a collection or processing problem dealing with lidar intensity attribute information.

[Data Source - D:\00\\_Nevada\QL1\\_Temp\\_Swaths](#)

[Result Path - D:\00\\_Nevada\Nevada\\_QL1\\_QC\C\\_3\ColorByIntensity.jpg](#)

