



Date: December 13, 2021 **Time:** 21:35:37 UTC

Employee: N. Guenther

Job Name: CA Salton Sea

Point ID: GCP_012

State: California

Latitude: 32 40 44.92206

Longitude: -115 31 32.50671

Address and/or Intersection: Hwy 98, Calexico

OBSERVATION METHOD

<input type="radio"/>	VRS GNSS	H RMS:	V RMS:	Duration:		
<input checked="" type="radio"/>	STATIC GNSS	Start Time: 21:35:37 UTC		End Time: 23:01:25 UTC		
<input type="radio"/>	Conventional Pairs VRS	Point Number: _____	RMS: _____	H: _____	V: _____	Duration: _____
<input type="radio"/>	Conventional Pairs STATIC	Point Number: _____	RMS: _____	H: _____	V: _____	Duration: _____
<input type="radio"/>	Occupied Point	Pt.# / HT: _____ / _____	B.S	Pt.# / HT: _____ / _____	F.S.	Pt.# / HT: _____ / _____
<input type="radio"/>	Back Sight Point	Distance: _____	Vertical Angle: _____	Angle: _____		
<input type="radio"/>	F.S. Point	Angle: _____	Vertical Angle: _____	Slope Dist: _____	Horizontal Dist: _____	

TYPE OF SURFACE

- PAVEMENT
- VEGETATION
- BARE SOIL
- NGS CONTROL

PICTURES

- Photos of area & setup

POINT RE-CHECK

Date: _____

Time: _____

Pt ID: _____

Description:

Sketch or Image of Area





POINT ID: GCP_012
MONUMENT PHOTO



**Control
GCP_012
Pavement**



POINT ID: GCP_012

NORTH PHOTO



**Control
GCP_012
Pavement**



POINT ID: GCP_012

EAST PHOTO



Control
GCP_012
Pavement



POINT ID: GCP_012
SOUTH PHOTO





POINT ID: GCP_012

WEST PHOTO



**Control
GCP_012
Pavement**