



Date: December 12, 2021 **Time:** 16:44:38 UTC

Employee: N. Guenther

Job Name: CA Salton Sea

Point ID: GCP_013

State: California

Latitude: 32 53 01.18280

Longitude: -115 24 21.44839

Address and/or Intersection: Harris Rd and Hwy 115

OBSERVATION METHOD

<input checked="" type="radio"/>	VRS GNSS	H RMS: 0.004		V RMS: 0.007		Duration:	
<input type="radio"/>	STATIC GNSS	Start Time:		UTC	End Time:		UTC
<input type="radio"/>	Conventional Pairs VRS	Point Number: _____	RMS: _____	H: _____	V: _____	Duration: _____	
<input type="radio"/>	Conventional Pairs STATIC	Point Number: _____	RMS: _____	H: _____	V: _____	Duration: _____	
<input type="radio"/>	Occupied Point	Pt.# / HT: _____ / _____	B.S	Pt.# / HT: _____ / _____	F.S.	Pt.# / HT: _____ / _____	
<input type="radio"/>	Back Sight Point	Distance: _____		Vertical Angle: _____		Angle: _____	
<input type="radio"/>	F.S. Point	Angle: _____	Vertical Angle: _____	Slope Dist: _____	Horizontal Dist: _____		

TYPE OF SURFACE

- PAVEMENT
- VEGETATION
- BARE SOIL
- NGS CONTROL

PICTURES

- Photos of area & setup

POINT RE-CHECK


Date: _____

Time: _____

Pt ID: _____

Description:

Sketch or Image of Area





POINT ID: GCP_013
MONUMENT PHOTO



Control
GCP_013
Bare Earth

12/12/2021



POINT ID: GCP_013
NORTH PHOTO



Control
GCP_013
Bare Earth

12/12/2021



POINT ID: GCP_013
EAST PHOTO



Control
GCP_013
Bare Earth

12/12/2021



POINT ID: GCP_013
SOUTH PHOTO




Control
GCP_013
Bare Earth

12/12/2021



POINT ID: GCP_013

WEST PHOTO



**Control
GCP_013
Bare Earth**

12/12/2021