

## **CHECK POINT DOCUMENTATION REPORT**

Date:	12-02-19	Time: <u>11:30</u>	⊠ a.m. □	p.m. Employee Name: Ryan	Daniel		
Job Na	ame: Florida Pen	insular LiDAR		Point ID: NVA 113 BE			
State: FL Latitude: 30° 00′ 09.98700″ N			⊠ + □ – Longitude: <u>83° 42′ 28.50900″</u>				+ 🛛 –
Addre	ss and/or Interse	ction: <u>Landfill Road</u>	Perry,	FL			
OBS	SERVATION	I METHOD					
×	VRS GPS	RMS:H:0.01	V: <b>0.02</b>	Duration: 180 SECONDS			
	STATIC GPS	Start Time: a.m.					
	Conventional Pairs VRS	Point Number:	RMS:_	H:V:_	Dura	tion:	
		Point Number:	RMS:_	H:V:	Dura	tion:	
	Conventional Pairs STATIC	Point Number: Start Time: a.m.				□ a.m. □ p.m.	
		Point Number:S	tart Time:	a.m. □ p.m	. End Time:		□ a.m. □ p.m.
□ Po	Occupied int	Pt. #/HT:/	□ BS	Pt. #/HT/	□ FS	Pt. #/HT	
	Back Site Point	Distance:	Vertical Angle:		☐ Angle	00°00′00″_	
	FS Point	Angle:Vertical Angle:		Slope Distance:	Horizontal Distance:		
TYPE OF SURFACE  Sketch or Image of Area							
NVA: OPEN Terrain							
□ VVA: GWC Terrain							
<b>□ v</b> v	A: BLT Terrain						1
□ VVA: Forested							
□ N\	/A: Urban Areas						
□ NO	GS Control				9NVA113	经过抵制	
PIC:	TURES				JUV/AII IS		

☑ Picture(s) of Area & Setup

## **POINT RE-CHECK**

Re-Check Point ID: #212

**Date:** <u>12/03/19</u> \_\_\_ □ a.m. ⊠ p.m.

**Description of Point:** 

Set 60D nail down a trail road ±300' west of

Landfill road; S to SW of a main trail and a side trail intersection; on edge of trail





