

CHECK POINT DOCUMENTATION REPORT

Date: 01/30/19 Time:	: <u>10:47</u> ⊠a.m. □ p.m.	Employee Name: ALBERTO MA	RTINEZ
Job Name: Florida Peninsular LiDA	R	Point ID: <u>NVA_377_AP</u>	(15075)
State: FL Latitude: 27 5	58 25.73996	_⊠ + □ – Longitude: <u>81 22 53.4</u>	8424 □ + ⊠ -

Address and/or Intersection: CAMP MACK DR, A GUY HARVEY LODGE, MARINA & RV RESORT

OBSERVATION METHOD

	VRS GPS	RMS:H: 0.008 V: 0.012 _Duration: _90 SECONDS							
	STATIC GPS	Start Time:	a.m. 🗆 p.m. End Time:			□ a.m.	□ p.m.		
	Conventional	Point Number:	RMS:	H:	V:	Dura	ation:		
	Pairs VRS	Point Number:	RMS:	H:	V:	Dura	ation:		
	Conventional Pairs STATIC	Point Number:	Start Time: a.m. □ p.m. End Time:			a.m. □ p.m.			
		Point Number:	Start Time:		a.m. 🗆 p.m. End Time:			□ a.m. □ p.m.	
	Occupied Point	Pt. #/HT:/	D BS	Pt. #/HT	/	□ FS	Pt. #/HT	/	
	Back Site Point	Distance:	Vertical Angle: _			Angle:	00°00′0	00″	
	Fore Site Point	Angle:	Vertical Angle:	Slop	e Distance:	Ha	rizontal Distance	e:	

TYPE OF LAND COVER

- □ NVA: OPEN Terrain
- VVA: GWC Terrain
- VVA: BLT Terrain
- VVA: Forested
- NVA: Urban Areas
- □ NGS Control

PICTURES

Picture(s) of Area & Setup

POINT RE-CHECK

Date: 05/30/19 _____ Time: 08:30 ____ A.m. □ p.m.

Re-Check Point ID: 15413

Description of Point: MND LB8011





