

Re-Check Point ID: 208

Description of Point:

Set PK nail at tip of arrow pointing NE exiting

parking area on South West end of parking lot

## **CHECK POINT DOCUMENTATION REPORT**

Date:	11-18-19	Time: 3:00	□ a.m. ⊠	p.m. <b>Employee Na</b>	ıme: <u>Ryan I</u>	Daniel		
Job N	lame: <u>Florida Per</u>	ninsular LiDAR		Point	ID: <u>NVA 7</u> 1	I_AR		
State:	e: <u>FL</u> Latitude: <u>30° 15′ 10.60778″ N</u>							
Addre	ess and/or Interse	ection: <u>10740 Dowling Par</u>	k Dr. L	ive Oak, FL. 32064				
OB:	SERVATION	N METHOD						
×	VRS GPS	RMS:H:0.0	1 V: <b>0.01</b>	Duration: 180	SECONDS			
	STATIC GPS	Start Time:	□ a.m. □	p.m. End Time:		□ a.m. □ p.m.		
	Conventional Pairs VRS	Point Number:	RMS:_	H:	V:	Dura	tion:	
		Point Number:	RMS:	H:	V:	Dura	tion:	
	Conventional Pairs STATIC	Point Number:	Start Time:		a.m. 🗆 p.m.	End Time:		a.m. □ p.m.
						End Time: a.m.		
P	Occupied	Pt. #/HT:/_	_ □ BS	Pt. #/HT	<i></i>	□ FS	Pt. #/HT	
	Back Site Point	Distance: Vertical An		le:		□ Angle00°00′00″		
	FS Point	Angle:Vertical Angle:		Slope Distance:		Horizontal Distance:		
TYF	E OF SURI	FACE	Sk	etch or Image of Ar	ea			
⊠ N	VA: OPEN Terrai	n	T <sub>1</sub>					
□ <b>v</b>	VA: GWC Terrain	ı		Design To				
□ <b>v</b>	VA: BLT Terrain					, O		
□ <b>v</b>	VA: Forested							
□ N	VA: Urban Areas			Palk				
□ N	GS Control			Contra	in			
PIC	TURES					-	1	
⊠ Pi	cture(s) of Area 8	k Setup	8		₩,,	117 8 1		Marvi
POI	NT RE-CHI	ECK			•	SRI S BI	1	gyJones Bivd
Date:	12/3/19	<b>Time<u>: 10:20</u></b> □ a.i	m. 🗆 p.m.	Fig. Mr.	and a	I AAA III		Blvd



