

CHECK POINT DOCUMENTATION REPORT

Date: <u>12-11-19</u>	-19 Time: 2:03		□ a.m. ⊠	p.m. Employ	ee Name: <u>Z. B</u>	arnes / J. Walker		
Job Name: <u>Florida Pe</u> i	ninsular LiDAR				oint ID: <u>NVA</u>	95 BE 148/14	9	
State: <u>FL</u> Latitude: 30° 10' 37.92944"								
Address and/or Inters	ection:							
OBSERVATIO	N METHOD							
⊠ VRS GPS	RMS:	H: 0.042	2 V: 0.04 0) Duration:	180 SECONDS	8		
□ STATIC GPS	Start Time: a.m. p.m. End Time: a.m. p.m.							
☐ Conventional Pairs VRS	Point Number: RMS: H: V: Duration: Point Number: RMS: H: V: Duration:					·	_	
☐ Conventional Pairs STATIC								a.m. □ p.m. a.m. □ p.m.
☐ Occupied Point	Pt. #/HT:	_/	□BS	Pt. #/HT		□FS	Pt. #/HT	/
☐ Back Site Point	Distance:		Vertical Angle:			_	00°00	0′00″
☐ FS Point	Angle:	le:Vertical Angle:		Slope Distance:		Ho	Horizontal Distance:	
TYPE OF SUR	FACE		Sk	etch or Image	of Area			
NVA: OPEN Terrai	in						Provide	
□ VVA: GWC Terrain	1			- T				
□ VVA: BLT Terrain					100			
□ VVA: Forested								
□ NVA: Urban Areas	•			M. K.				

PICTURES

☐ NGS Control

☑ Picture(s) of Area & Setup

POINT RE-CHECK

Date: 12/12/19 Time: 2:00 □ a.m. ⊠ p.m.

Re-Check Point ID: 160

Description of Point:

NL/60D in front of gate on PJ road and Tiger Lake

Rd





