

CHECK POINT DOCUMENTATION REPORT

Date: <u>11-13-19</u>		Time: <u>9:0</u>	0	⊠ a.m. □	p.m. Employe e	e Name: <u>R</u> ı	yan Daniel			
Job Name: Florida Peninsular LiDAR				Point ID: VVA 12 BLT						
State:	<u>FL</u> 1	Latitude: <u>30° 24′ 45.53628″ N</u>		⊠ + □ - Longitude: 83° 37′ 42.05776″						
Addre	ess and/or Interse	ction: <u>663-671 S</u>	SW Dupont	St.	Greenville, FL. 3	2331				
ОВ	SERVATION	N METHOD								
×	VRS GPS	RMS:	H: 0.01	V: 0.02	2Duration: _	180 SECON	DS			
	STATIC GPS	Start Time:								
	Conventional	Point Number:_		RMS:	H:	\	V:	Dura	ition:	
	Pairs VRS	Point Number:_		RMS:_	H:		V:	Dura	ition:	
	Conventional	Point Number:_	S	Start Time: a.m.						a.m. □ p.m.
	Pairs STATIC	Point Number:_	S	art Time:		_□ a.m. □ p	o.m. End Ti	me:		□ a.m. □ p.m.
P	Occupied	Pt. #/HT:	_/	□ BS	Pt. #/HT	/] FS	Pt. #/HT	/
	Back Site Point Distance: Vertica			Vertical Angle	al Angle:			Angle	00°00′0	<u>0"</u>
	FS Point	Angle:	Verti	cal Angle:	Slop		Horizontal Distance:			
TYF	E OF SURF	FACE		Sk	etch or Image o	f Area				
□ N	IVA: OPEN Terraiı	n		П	PROPERTY NEW		high April		A. 1853 A. 18	计是内部的 第0
□ v	VA: GWC Terrain				第四个				1. 大大线	是 本 5 元
				17500 45		1		这位的		
□ v	VA: Forested				Min.			+ 18 J		30
□ NVA: Urban Areas				SW 76th And						
□ NGS Control					N. W.	VVA_12_BLT	0			70 180 70
PICTURES						1 14	=			A STATE OF

POINT RE-CHECK

☑ Picture(s) of Area & Setup

Date: 11/14/19 Time: 7:37 _____⊠ a.m. □ p.m. Re-Check Point ID: 84 **Description of Point:**

Set CIR/8011 TRAV ±30' South of centerline of sw dupont street



