

Re-Check Point ID: 1231

Description of Point:

coverage to thick

CIR / 5-8 8011 Trav moved FO to GWC / tree

CHECK POINT DOCUMENTATION REPORT

Date: 11-13-19 Time: 3:02 □ a.m. ☑ p.m. Employee Name: Z. Barnes / J. Walker								
Job Name: Florida Peninsular LiDAR			Point ID: <u>VVA_5_GWC</u> 1177-1178					
State: FL Latitude: 30° 35′ 44.75910″ N								
Address and/or Interse	ection: <u>Moved point to intersection</u>	section from BL	T & BE					
⊠ VRS GPS	RMS:H:0.01	5 V: 0.01 6	Duration: 180	SECONDS				
□ STATIC GPS	Start Time:	□ a.m. □] p.m. End Time: a.			m. □ p.m.		
☐ Conventional Pairs VRS	Point Number:					<u> </u>		
☐ Conventional Pairs STATIC	Point Number:S	tart Time:		a.m. 🛮 p.m. E	End Time:		a.m. 🗆 p.m.	
	Point Number:S	tart Time:	a.m. □ p.m. End Time: □ a.m				□ a.m. □ p.m.	
☐ Occupied Point	Pt. #/HT:/	□ BS	Pt. #/HT	/	□ FS	Pt. #/HT	/	
□ Back Site Point	Distance:	Vertical Angle:	e:			<u>'0"</u>		
☐ FS Point	Angle:Vertical Angle:		Slope Dis	Horizontal Distance:				
TYPE OF SUR	FACE	Ske	etch or Image of Are	∍a				
□ NVA: OPEN Terrai	n				The State of the S	这名为于		
□ VVA: BLT Terrain								
□ VVA: Forested						The second		
□ NVA: Urban Areas	;				*		The second second	
□ NGS Control				A CONTRACTOR OF THE PARTY OF TH				
PICTURES			7 B 12	举法	•WA 5			
☑ Picture(s) of Area &								
POINT RE-CHI	ECK			36th Dr				
Date <u>: 11/19/19 </u>								



