

Re-Check Point ID: <u>277</u>

Description of Point:

Set 60D nail down a trail road in forest opening ±100' from center line of county road 252

CHECK POINT DOCUMENTATION REPORT

Date: 11-19-19	Time: 10:0	00	_⊠ a.m. □	p.m. Employee	e Name: Ryar	n Daniel			
Job Name: Florida Peninsular LiDAR				Po	oint ID: <u>VVA</u>	50_FO			
State: FL Latitude: 30° 10′ 23.79617″ N				⊠ + □ - Longitude: <u>83° 02′ 33.73196″</u> □ + ⊠					
Address and/or Interse	ction: <u>14370 Co</u>	unty Road 252		Live Oak, FL	. 32060				
OBSERVATION	I METHOD								
⊠ VRS GPS	RMS:	H: 0.01	V: 0.03	Duration: _	180 SECONDS	<u> </u>			
☐ STATIC GPS	Start Time: a.m.			p.m. End Time	:	a.m.	a.m.		
☐ Conventional Pairs VRS	Point Number:RMS								
☐ Conventional Pairs STATIC	Point Number:Start Time: Point Number:Start Time:								
☐ Occupied Point	Pt. #/HT:	_/	□BS	Pt. #/HT		□ FS	Pt. #/HT		
☐ Back Site	Distance: Vertical Ang			∷			00°00′	00"	
☐ FS Point	Angle:Vertical Angle:			Slope Distance:Horizo			rizontal Distand	ce:	
TYPE OF SURFACE Sketch or Image of Area									
□ NVA: OPEN Terrain								W River	
□ VVA: GWC Terrain							5.60		
□ VVA: BLT Terrain					TE STEVE		2017	252	
☑ VVA: Forested									
□ NVA: Urban Areas □ NGS Control				VVA	_50_FO		大		
PICTURES ☑ Picture(s) of Area &				I					
POINT RE-CHECK									
Date: 12/9/19									



