

Re-Check Point ID: ____
Description of Point:

Set 60D nail in low brush area ± 60' W/NW of a shooting stand ; ± 8' North of trail road leading to point

CHECK POINT DOCUMENTATION REPORT

Date: 11-11-19	Time: <u>3:4</u>	<u>0</u> □ a.m. ⊠	p.m. Employee Name:_	Ryan Daniel		
Job Name: <u>Florida Pen</u>	insular LiDAR		Point ID:	VVA_6_BLT		
State: <u>FL</u> Latitude: <u>30° 30′ 01.13549″ N</u>		01.13549" N	⊠ + □ − Longitude: 83° 31′ 48.96574″ W			
Address and/or Interse		6 NW Elizabeth Sims Loop	o Greenville, FL 3233	i 1		
⊠ VRS GPS	RMS:	H: 0.01 V: 0.01	Duration: 180 SECC	ONDS		
☐ STATIC GPS						
☐ Conventional Pairs VRS					ation:	
☐ Conventional Pairs STATIC					End Time: □ a.m. □ p.m. End Time: □ a.m. □ p.m	
☐ Occupied Point	Pt. #/HT:	_/ 🗆 BS	Pt. #/HT/_		Pt. #/HT/	
☐ Back Site Point	Distance:	Vertical Angle:	:		00°00′00″	
☐ FS Point	Angle:	Vertical Angle:	Slope Distance	e:Ho	Horizontal Distance:	
TYPE OF SURF	FACE	Sk	xetch or Image of Area			
□ NVA: OPEN Terrain	n	I	THE SE	11214114	新教员 (1981年) (1987年)	
□ VVA: GWC Terrain	ı	N	Control of the second			
		18				
□ VVA: Forested			161			
□ NVA: Urban Areas				8 3	137.14	
□ NGS Control				VVA_6	ВЦТ	
PICTURES					S STATE OF THE STA	
☑ Picture(s) of Area &	Setup		· ZZ			
POINT RE-CHE	ECK				att pality	
Date:	Time:	□ a.m. □ p.m.	AREAN WAY		A STATE OF THE STA	



