

Re-Check Point ID: ____
Description of Point:

roads centerline

Set 60D nail in brushland area ±50' East of a trail

CHECK POINT DOCUMENTATION REPORT

Date: <u>12-04-19</u>	Time: 10:25	⊠ a.m. □	p.m. Employee Name: Ryan	<u>Daniel</u>	
Job Name: Florida Pen	ninsular LiDAR		Point ID: VVA_7	7_BLT	
State: FL I			⊠ + □ - Longitude: <u>83</u>		
Address and/or Interse		o name) in Mayo, FL	(West of Hwy 51)		
☑ VRS GPS	RMS:H	i: 0.01 V: 0.01	_Duration: <u>180 SECONDS</u>		
□ STATIC GPS			p.m. End Time:	·	
☐ Conventional Pairs VRS			H:V: H:V:		
☐ Conventional Pairs STATIC			a.m. □ p.m. a.m. □ p.m.		
☐ Occupied Point	Pt. #/HT:/	🗆 BS	Pt. #/HT/_	□ FS Pt. #/HT	
□ Back Site Point	Distance:	Vertical Angle:		☐ Angle00°00′0	00"
☐ FS Point	Angle:	Vertical Angle:	Slope Distance:	Horizontal Distanc	:e:
TYPE OF SURFACE Sketch or Image of Area					
□ NVA: OPEN Terrain	n		***	MATARIA	
□ VVA: GWC Terrain	I	5		从 。这是是是是	
□ VVA: Forested			I A COLOR		
□ NVA: Urban Areas				VVA_77_BLT	1.7
□ NGS Control					
PICTURES			7.40	建筑线机 空机等	
☑ Picture(s) of Area & Setup					
POINT RE-CHECK					
Date:	Time:	□ a.m. □ p.m.		41.75	



