

CHECK POINT DOCUMENTATION REPORT

| Date: <u>11-21-19</u> | Time: <u>10:00</u> | _⊠ a.m. □ p.m. Employee Name: <u>Ryan Daniel</u> | |
|-------------------------------|-------------------------------|--|-------|
| Job Name: <u>Florida Pe</u> r | ninsular LiDAR | Point ID: VVA 92 GWC | |
| State: FL | Latitude: 29° 55' 17.66475" N | ⊠ + □ – Longitude: <u>83° 02′ 51.79925″</u> | + 🛛 – |
| | | | |

Address and/or Intersection: Branford, FL

OBSERVATION METHOD

| ⊠ VRS GPS | RMS:H:_ | 0.01 V: 0.01 | Duration: <u>180 SECONDS</u> | <u>; </u> | |
|---------------------------------|---------------|-----------------|------------------------------|--|-----------------|
| □ STATIC GPS | Start Time: | art Time: a.m. | | |] p.m. |
| Conventional Pairs VRS | Point Number: | RMS: | H:V: | Duratio | on: |
| | Point Number: | RMS: | H:V:_ | Duratio | on: |
| Conventional Pairs STATIC | Point Number: | Start Time: | a.m. 🗆 p.m. End Time: | | □ a.m. □ p.m. |
| | Point Number: | Start Time: | a.m. 🗆 p.m. End Time: | | □ a.m. □p.m. |
| ☐ Occupied Point | Pt. #/HT:/ | BS | Pt. #/HT/ | □ FS | Pt. #/HT/ |
| Back Site Point | Distance: | Vertical Angle: | | _ 🗆 Angle – | 00°00'00" |
| □ FS Point | Angle: | Vertical Angle: | Slope Distance: | Horiz | ontal Distance: |

TYPE OF SURFACE

- NVA: OPEN Terrain
- VVA: GWC Terrain
- VVA: BLT Terrain
- VVA: Forested
- □ NVA: Urban Areas
- □ NGS Control

PICTURES

☑ Picture(s) of Area & Setup

POINT RE-CHECK

Date:_____□ a.m. □ p.m.

Re-Check Point ID:

Description of Point: Set 60D nail at end of a trail road ±10' from swamp or wetland area

Sketch or Image of Area





