

Date:	01/04/19	Time: <u>07:4</u>	3	⊠ a.m. □	p.m. <b>Employee</b>	Name: <u>Alberto</u>	Martinez		
Job Na	ame: <u>Florida Pen</u>	insular LiDAR			Po	int ID: <u>15034 (G</u>	CP AXIS 6)		
State: <u>FL</u> Latitude: <u>28°15′11.18761″ N</u>				<u>⊠</u> + □ − <b>Longitude</b> : <u>81°34′21.02416″ W</u>				+ 🛛 –	
Addre	ss and/or Interse	ction: <u>Cypress P</u>	ointe Boul	evard / Old Lak	ce Wilson Road				
OBS	SERVATION	METHOD							
⊠	VRS GPS	RMS:	H: <u>0.012</u>	V: <u>0.018</u>	Duration: <u></u>	90 seconds			
	STATIC GPS	Start Time: a.m.							
П	Conventional Pairs VRS	Point Number:		RMS:	H:	V:	Dura	ition:	
		Point Number:		RMS:	H:	V:	Dura	ition:	
	Conventional Pairs STATIC	Point Number:	Point Number:Start Time:			□ a.m. □ p.m.End Time:			
		Point Number:	S	tart Time:		_□ a.m. □ p.m.E	End Time:		□ a.m □ p.m.
	Occupied Point	Pt. #/HT:	_/_	□ BS	Pt. #/HT		□ FS	Pt. #/HT	
	Back Site Point	Distance: _		Vertical Angle:			☐ Angle	00°00	0'00"
	FS Point	Angle:VerticalAngle:		Slope	Slope Distance:		Horizontal Distance: _		
				Ske	etch or Image o	f Area			
TYP	E OF SURI	FACE							
⊠ PA	VEMENT					The state of the s			
□ мо	WED GRASS			*					2 30
□ BARE SOIL					COP A GOP A	Marie e			
□ NGS Control									

## **PICTURES**

☑ Picture(s) of Area & Setup

## POINT RE-CHECK

Date:01/14/19	_Time: <u>1:24</u>	□ a.m. 🛛 p.m.						
Re-Check Point ID:	15054							
Description of Point:								
SET MND "TRAV PNT LB 8011"								





