

Date:	02-07-19	Time: <u>3:46</u>	S	□ a.m. ⊠	p.m. Employe e	Name: ANDY B	BROWN		
					Point ID: <u>GCP_DAS 8 (70095)</u>				
					⊠ + □ − Longitude: <u>83 37 56.70131</u>				
2 (a)	W			201.004		-			
Addre	ess and/or Interse	ection: <u>STATE H</u>	<u>WY 14 & HV</u>	/Y 221					
OBS	SERVATION	METHOD							
×	VRS GPS	RMS:	H: 0.01	V: 0.02	Duration: 1	180 SECONDS			
	STATIC GPS				☐ p.m. End Time:		a.m. [l □ p.m.	
	Conventional	Point Number:_		RMS:_	H:	V:	Dura	tion:	
	Pairs VRS	Point Number:_		RMS:_	H:	V:	Dura	tion:	
	O	Point Number:_	S	tart Time:		_□ a.m. □ p.m.	End Time:		□ a.m. □ p.m.
	Conventional Pairs STATIC	Point Number:_	s	tart Time:		_□ a.m. □ p.m. l	End Time:		□ a.m. □ p.m
	Occupied Point	Pt. #/HT:		□ BS	Pt. #/HT		□FS	Pt. #/HT	
	Back Site Point	Distance:		Vertical Angle	e:		☐ Angle	00°00	<u>)'00"</u>
	Fore Site Point	Angle:Vertical Angle:			Slope Distance:Horizontal Distance:				ice:
TYP	PE OF SURI	FACE		_					
	VEMENT			Ś	Sketch or Image	of Area			
	OWED GRASS								
□ВА	ARE SOIL								
□ NG	GS Control				Carles !				
	TUDEO								
	TURES	9 Cotun							
, ,							GCP_DAS 8		
POINT RE-CHECK									
Date: a.m. □ p.m. Re-Check Point ID:					A PARTY OF THE PAR		8	The state of	
Re-Cr	ieck Point ID:				d the				
Description of Point: MND LB8011					Googless:1	Sima Visita via via	.anuqui.		



