

Dato:	02/06/19	Time: <u>12:0</u> 2	,	□ o m . M	nm Employee	Namo: Andy P	rown		
Date.	02/06/19	Time: 12:02	2	⊔ a.m. ⊠	p.m. Employee	Name: Andy B	rown		
Job Na	ame: Florida Pen	insular LiDAR			Po	int ID: OL 6			
State: FL Latitude: 30°07′03.57018″ N				<u></u> ⊠ + □ − Longitude: 82°47′08.92936″ W				□ + 🖾 –	
Addre	ss and/or Interse	ction: <u>SW Cypres</u>	s Lake Ro	oad & SW Coun	ty Road 242				
ОВ	SERVATION	METHOD							
×	VRS GPS	RMS:	H: <u>0.01</u>	V: <u>0.01</u>	Duration: <u>{</u>	90s			
	STATIC GPS	Start Time: a.m.			p.m. End Time	<u>:</u>	□ a.m. □ p.m.		
	Conventional Pairs VRS	Point Number:		RMS:_	H:	V:	Dura	Duration:	
		Point Number:		RMS:_	H:	V:	Dura	Duration:	
	Conventional Pairs STATIC	Point Number:	Start Time:		a.m. □ p.m.		End Time:		□ a.m. □ p.m
		Point Number:	Start Time:			_□ a.m. □ p.m.l	End Time:	nd Time:	
Po	Occupied pint	Pt. #/HT:	/	□ BS	Pt. #/HT		□ FS	Pt. #/HT	
	Back Site Point	Distance: Vertical Ang					□ Angle00°00′00″		2′00″
	FS Point	Angle:Vertical Angle:			Slope Distance:		Horizontal Distance		ce:
				Sk	etch or Image of	f Area			
TYP	E OF SURI	FACE					100 100 100 100 100 100 100 100 100 100		P 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
☑ PAVEMENT						SW-Sa	bria.		
☐ MOWED GRASS					lem-R				
□ BARE SOIL									

☐ NGS Control

PICTURES

☑ Picture(s) of Area & Setup

POINT RE-CHECK

____**Time:** <u>5:38</u> □ a.m. ⊠ p.m. Date:02/07/19

Re-Check Point ID: PT 70579

Description of Point: <u>Corner of Stop Bar on SW Cypress</u> <u>Lake Road MND LB 8011</u>





