Dewberry GROUND CONTROL POINT DOCUMENTATION REPORT

Date: 12/19/18 **Time:** 04:32 ☐ a.m. ☒ p.m. **Employee Name:** Andrew Strickland

Job Name: Florida Peninsular LiDAR **Point ID:** 60003 (GCP QSI 102)

State: FL **Latitude:** 29°16'24.89910"N ☒ + ☐ – **Longitude:** 81°29'50.26494"W ☐ + ☒ –

Address and/or Intersection: PI Old Bubbly Road / Nine Mile Point Road

OBSERVATION METHOD

☒ **VRS GPS**	RMS:_____ H: 0.090 V: 0.083 Duration: 90 seconds				
☐ **STATIC GPS**	Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ a.m. ☐ p.m. ☐				
☐ **Conventional Pairs VRS**	Point Number:_____ RMS:_____ H:_____ V:_____ Duration:_____ Point Number:_____ RMS:_____ H:_____ V:_____ Duration:_____				
☐ **Conventional Pairs STATIC**	Point Number:_____ Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ ☐ a.m. ☐ p.m. Point Number:_____ Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ ☐ a.m ☐ p.m.				
☐ **Occupied Point**	Pt. #/HT:_____/_____	☐ **BS**	Pt. #/HT_____/_____	☐ **FS**	Pt. #/HT_____/_____
☐ **Back Site Point**	Distance:_____ Vertical Angle:_____		☐ **Angle**	00°00'00"	
☐ **FS Point**	Angle:_____ Vertical Angle:_____ Slope Distance:_____ Horizontal Distance:_____				

TYPE OF SURFACE

☐ **PAVEMENT**

☐ **MOWED GRASS**

☒ **BARE SOIL**

☐ **NGS Control**

PICTURES

☒ **Picture(s) of Area & Setup**

POINT RE-CHECK

Date: 12/21/18 **Time:** 12:18 ☐ a.m. ☒ p.m.

Re-Check Point ID: 60011

Description of Point:

SET MND "TRAV PT LB 8011"

Sketch or Image of Area


GCP_QSI_102


GCP_QSI 102
CA102
(60003)