Dewberry

GROUND CONTROL POINT DOCUMENTATION REPORT

Date: 01/08/19   **Time:** 12:00   ☐ a.m. ☒ p.m. **Employee Name:** Andrew Strickland

Job Name: Florida Peninsular LiDAR   **Point ID:** (GCP QSI 28) 60070

State: FL   **Latitude:** 30°26'44.99480"N   ☒ + ☐ – **Longitude:** 81°40'23.45059"W   ☐ + ☒ –

Address and/or Intersection: Longwood Key Drive N. / Coral Ridge Ave

OBSERVATION METHOD

☒	**VRS GPS**	RMS:_____ H:0.041 V:0.002 Duration: 90 seconds _____
☐	**STATIC GPS**	Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ a.m. ☐ p.m. ☐
☐	**Conventional Pairs VRS**	Point Number:_____ RMS:_____ H:_____ V:_____ Duration:_____ Point Number:_____ RMS:_____ H:_____ V:_____ Duration:_____
☐	**Conventional Pairs STATIC**	Point Number:_____ Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ ☐ a.m. ☐ p.m. Point Number:_____ Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ ☐ a.m. ☐ p.m.
☐	**Occupied Point**	Pt. #/HT:_____/___ ☐ **BS** Pt. #/HT_____/_____ ☐ **FS** Pt. #/HT_____/_____
☐	**Back Site Point**	Distance:_____ Vertical Angle:_____ ☐ **Angle** ____00°00'00"____
☐	**FS Point**	Angle:_____ Vertical Angle:_____ Slope Distance:_____ Horizontal Distance:_____

TYPE OF SURFACE

☒ PAVEMENT

☐ MOWED GRASS

☐ BARE SOIL

☐ NGS Control

PICTURES

☒ Picture(s) of Area & Setup

POINT RE-CHECK

Date: 01/08/19   **Time:** 04:05   ☐ a.m. ☒ p.m.

Re-Check Point ID: 60076

Description of Point: _____

SET LG Mag N&D Stamped "TRAV PT   LB 8011"

Sketch or Image of Area

GCP_QSI 28
CA 28
60070

GCP_QSI_28