Dewberry GROUND CONTROL POINT DOCUMENTATION REPORT

Date: 02/21/19 **Time:** 02:04 ☐ a.m. ☒ p.m. **Employee Name:** Micheal Tadros

Job Name: Florida Peninsular LiDAR **Point ID:** (GCP QSI 62) 15259

State: FL **Latitude:** 29°53′57.62477″ N ☒ + ☐ – **Longitude:** 82°04′23.02241″ W ☐ + ☒ –

Address and/or Intersection: Intersection of Boot Drain road and SE 125th Terrace

OBSERVATION METHOD

☒ **VRS GPS**	RMS:_____ H:0.014 V:0.024 Duration: 90 seconds				
☐ **STATIC GPS**	Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ a.m. ☐ p.m. ☐				
☐ **Conventional Pairs VRS**	Point Number:_____ RMS:_____ H:_____ V:_____ Duration: _____ Point Number:_____ RMS:_____ H:_____ V:_____ Duration: _____				
☐ **Conventional Pairs STATIC**	Point Number:_____ Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ ☐ a.m. ☐ p.m. Point Number:_____ Start Time:_____ ☐ a.m. ☐ p.m. End Time:_____ ☐ a.m ☐ p.m.				
☐ **Occupied Point**	Pt. #/HT:_____/___	☐ **BS**	Pt. #/HT_____/_____	☐ **FS**	Pt. #/HT_____/_____
☐ **Back Site Point**	Distance: _____ Vertical Angle: _____		☐ **Angle**	00°00′00″	
☐ **FS Point**	Angle:_____ Vertical Angle:_____ Slope Distance:_____ Horizontal Distance: _____				

TYPE OF SURFACE

☒ **PAVEMENT**

☐ **MOWED GRASS**

☐ **BARE SOIL**

☐ **NGS Control**

PICTURES

☒ **Picture(s) of Area & Setup**

POINT RE-CHECK

Date:_____ **Time:**_____ ☐ a.m. ☐ p.m.

Re-Check Point ID: _____

Description of Point: _____

SET MAG N&D Stamped "TRAV PT LB 8011"

Sketch or Image of Area

GCP_QSI 62

GCP_QSI 62