

Date: 02/07/19 Time: 1:35 a.m. p.m. Employee Name: Andrew Strickland

Job Name: Florida Peninsular LiDAR Point ID: (GCP QSI 77) 60205

State: FL Latitude: 29°43'07.02593"N + - Longitude: 81°32'44.58909"W + -

Address and/or Intersection: 137 Mays Cove Road

OBSERVATION METHOD

<input checked="" type="checkbox"/> VRS GPS	RMS: _____ H: <u>0.021</u> V: <u>0.100</u> Duration: <u>90 seconds</u>				
<input type="checkbox"/> STATIC GPS	Start Time: _____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m. End Time: _____ a.m. <input type="checkbox"/> p.m. <input type="checkbox"/>				
<input type="checkbox"/> Conventional Pairs VRS	Point Number: _____ RMS: _____ H: _____ V: _____ Duration: _____				
	Point Number: _____ RMS: _____ H: _____ V: _____ Duration: _____				
<input type="checkbox"/> Conventional Pairs STATIC	Point Number: _____ Start Time: _____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m. End Time: _____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.				
	Point Number: _____ Start Time: _____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m. End Time: _____ <input type="checkbox"/> a.m. <input type="checkbox"/> p.m.				
<input type="checkbox"/> Occupied Point	Pt. #/HT: _____ / _____	<input type="checkbox"/> BS	Pt. #/HT: _____ / _____	<input type="checkbox"/> FS	Pt. #/HT: _____ / _____
<input type="checkbox"/> Back Site Point	Distance: _____ Vertical Angle: _____		<input type="checkbox"/> Angle _____ 00°00'00"		
<input type="checkbox"/> FS Point	Angle: _____ Vertical Angle: _____ Slope Distance: _____ Horizontal Distance: _____				

Sketch or Image of Area

TYPE OF SURFACE

- PAVEMENT
- MOWED GRASS
- BARE SOIL
- NGS Control

PICTURES

- Picture(s) of Area & Setup

POINT RE-CHECK

Date: 03/21/19 Time: 11:20 a.m. p.m.

Re-Check Point ID: 60290

Description of Point: _____

SET 5/8" MND Stamped "TRAV PT LB 8011"



