


Data Validation Report

from the National Geospatial Technical Operations Center in Support of the 3D Elevation Program

GA SW Georgia B5 2017

2022-01-13







1 of 3 Project Name: GA_SW Georgia 22 County Lidar_2017_B17

Report Date: 2022-01-13

Based on this review, the delivered data is **EXPECTED TO MEET** 3D Elevation Program requirements.

Work Unit Summary Information

Project Name: GA_SW Georgia 22 County Lidar_2017_B17	Project ID: 70861	Project ID: 70861			
WU Name: GA_SW_Georgia_B5_2017	Work Unit ID: 195779	Work Unit ID: 195779			
Mechanism: GPSC	Lidar Base Spec: 1.2	Lidar Base Spec: 1.2			
Quality Level: 2	P-Method: 7 - Linear-Mo	P-Method: 7 - Linear-Mode Lidar			
Horizontal EPSG Code: 6445	Vertical EPSG Code: 6360	Geoid Model: GEOID 12B			
The National Map Help Desk Email: tnm_help@usgs.gov					

The U.S. Geological Survey evaluates absolute vertical accuracy of the lidar and lidar-derived bare earth digital elevation model (DEM) data at the project level. Data are produced to meet 9.8 cm absolute vertical accuracy at the 95-percent confidence level in non-vegetated, open terrain. To review vertical accuracy results, please see the project report

Breaklines

Based on this Review, the USGS-NGTOC ACCEPTS the Breaklines

Breaklines are visually reviewed in conjunction with the bare earth DEM for spatial and geometric accuracy. Breaklines are confirmed to be three dimensional (3D) features and that elevations are at or just below the immediately surrounding terrain. Single- and double-line drainages are reviewed to ensure downstream flow. The USGS recognizes that differences in collection methodology, resampling techniques, and other factors that are unique to proprietary production do occur, and these will result in minor horizontal and vertical differences between breaklines derived on the fly.

Error Type	Subtype	Quantity
------------	---------	----------

Reporting Metadata

Based on this Review, the USGS-NGTOC ACCEPTS the Reporting Metadata

Reports from the contractor, including calibration, collection, and processing methods, are reviewed for accurate information. For more information, please see the work units metadata.

Error Type	Subtype	Quantity
		~~~~

FGDC XML Metadata

Based on this Review, the USGS-NGTOC ACCEPTS the FGDC XML Metadata

CSGDM .xml metadata are parsed using the USGS Geospatial Metadata Validation Service and reviewed for accurate information. CSDGM is maintained by the Federal Geographic Data Committee (FGDC).

Error Type	Subtype	Ouantity
-:: O: :	Jubijpe	- Qualities





2 of 3 Project Name: GA_SW Georgia 22 County Lidar_2017_B17

Report Date: 2022-01-13

Spatial Metadata

Based on this Review, the USGS-NGTOC ACCEPTS the Spatial Metadata

Spatial metadata from the contractor, including raster and vector datasets, are evaluated together with pertinent deliverables for geometric fidelity and attribution accuracy. For more information, please see the work units metadata.

Error Type Quantity Subtype

Raster Metadata Based on this Review, the USGS-NGTOC ACCEPTS the Raster Metadata None

Quantity

DEM

Error Type

Based on this Review, the USGS-NGTOC ACCEPTS the DEM

Visual review is performed on .tif bare earth rasters at a 1:5,000 or larger viewing scale to validate point cloud geometry, raster processing methodology, point classification, and breaklines. Comprehensive review is completed to ensure consistency and accuracy across all files. For additional information, please see this work units metadata folder.

Error Type Subtype Quantity

Subtype

Pointcloud

Based on this Review, the USGS-NGTOC ACCEPTS the Pointcloud

Visual and statistical review is performed on classified .las files to validate adherence to contracted specifications. A comprehensive review is completed to ensure consistency and accuracy across all files, including the spatial reference system. Classification verification is limited to the minimum required by applicable Lidar Base Specification. Classifications beyond the minimum are not verified by USGS. LAS files are evaluated to ensure the public header block, point data records, and variable/extended variable length records are correctly populated. For additional information, please see the work units metadata folder.

Quantity Subtype Error Type





3 of 3 Project Name: GA_SW Georgia 22 County Lidar_2017_B17

Report Date: 2022-01-13