Elevation QA Review Report

Project: CO_GrandCounty_2010	Contract ID: 1100116
Liaison: John Murphey Partner(s):	Contractor: Aero-Metric, INC.
Data Delivery Date: January 3, 201 Date Data Reviewed: J	anuary 10, 20
Reviewer: Kimberly Robinson Total Square Miles Ro	eviewed: 438 sq. m
Elevation Type: LIDAR Format: .img Grid Spacing: 0.7	meters Tile size: 1500 x 15
Projection: UTM Zone: 13	atum: NAD83 Units: Meters
Licensing: Public Domain Metadata: Project Level	
Materials Received:	
Breakline Shapefiles	
Classified .las files	
Control Check files (control points)	
Bare Earth .img files	
Intensity files	
Vertical Accuracy Test Performed: Yes Test Point Source 0.056	ee: Contractor RMSE:

Vertical Accuracy Test Notes:

20 test points were provided in .shp format. No vertical accuracy test points were located in the small area of interest in Larimer county, so vertical accuracy for this area (Larimer county) could not be determined. I have included an updated vertical accuracy points shapefile with coordinates, lidar block, diff in z and diff in z squared on the external hard drive provided to USGS.

QA Review Summary:

All of the Colorado Grand County/Park County/Larimar County data was reviewed. No tile index shape file was sent with this data. No bounding shapefile for Grand County was sent with this data. This data was brought into Global Mapper as .img files. Errors were found throughout this project. There are possible seamlines in the data, water bodies greater than 2.0 acres that are not leveled, and one area where lidar elevation was significantly different than surrounding points with no explanation. I have included shapefiles that encompass the above areas on the external hard drive received. I regridded this data to 1/9th arc deg files in an attempt to fill in the missing data at possible seamlines, however, was unsuccessful. This data is rejected.


See JPEG examples low.

CONCLUSIONS: 1.95 % of artifacts removed

2. 95 % of vegetation penetrated

3. 98 % of buildings removed

CO_Grand County Project Area



CO_Grand County Project Area

-	- 5	6	E	E	=	6	E	=	€	E	E	E	E	E	€ .	8	E .	<u> </u>	<u>e</u>
5000 m	m 00000	25000 m	30000 m	35000 m	440000 m	45000 m	450000 m	455000 m	460000 m	465000 m	470000 m	475000 m	480000 m	485000 m	490000 m	495000 m	500000 m	505000 m	510000 m
		=		914															
			and the			12-00000												445	5000 1
																		445	0000 1
	15	A. A.		TO THE REAL PROPERTY.															
	377								-				y 8		:			444	5000
	-th	79.16	MI	UNI														444	0000
	e la			-	H	55			-										
100		16		1000		0:-			=====		-							443	5000
新																		443	0000
	0	在表现	西	4) is	2 2		- di										
-	1	1				10	S 7	77	- 10	-	-		2		- 1			442	5000
	Paris					US.	3 %						2 2					442	0000
																			5000
-	48					SE .												441	5000
	48	15				63							2	2 4				441	0000
																		440	5000
32 34						1	-											440	2000
																		440	0000
																		439	5000
-			-															439	0000
																		438	5000
\$81 BV	of to												8						
	0.00													2 0				438	0000
																		437	5000
			1																

CO Grand County Vertical Accuracy Testing Worksheet

		Vertical A	Accuracy Sta	tistic Workshee	t			
		COL	ORADO GRA	ND COUNTY				
Point	Easting	Northing	Point	Lidar	Z	z		
					Test point	Lidar value		(diff in
number	UTM (m)	UTM (m)	description	Block	value (m)	(m)	diff in z	z) ²
1	4459433.599	428723.152	Unknown	Grand County	2653.569	2653.654	-0.085	0.007
2	4457642.824	429212.687	Unknown	Grand County	2658.460	2658.486	-0.026	0.001
7	4454893.278	424939.954	Unknown	Grand County	2778.428	2778.455	-0.027	0.001
9	4451528.620	424610.627	Unknown	Grand County	2620.656	2620.658	-0.002	0.000
11	4447349.014	423307.270	Unknown	Grand County	2533.983	2533.963	0.020	0.000
12	4444458.632	419661.499	Unknown	Grand County	2484.116	2484.123	-0.007	0.000
14	4448002.782	415354.379	Unknown	Grand County	2516.179	2516.097	0.082	0.007
16	4440217.573	414580.477	Unknown	Grand County	2378.270	2378.230	0.040	0.002
18	4456072.052	430455.848	Unknown	Grand County	2558.540	2558.595	-0.055	0.003
21	4442938.063	430153.223	Unknown	Grand County	2556.182	2556.260	-0.078	0.006
22	4438486.713	425949.906	Unknown	Grand County	2596.993	2597.037	-0.044	0.002
24	4433870.744	423798.627	Unknown	Grand County	2596.138	2596.098	0.040	0.002
26	4431618.213	419819.121	Unknown	Grand County	2484.253	2484.125	0.128	0.016
28	4429493.045	420811.480	Unknown	Grand County	2583.335	2583.351	-0.016	0.000
30	4425994.482	425787.994	Unknown	Grand County	2577.914	2577.906	0.008	0.000
33	4419914.274	426603.500	Unknown	Grand County	2695.114	2695.109	0.005	0.000
34	4422237.032	430173.170	Unknown	Grand County	2610.842	2610.885	-0.043	0.002
35	4420057.463	432691.881	Unknown	Grand County	2656.175	2656.198	-0.023	0.001
37	4434409.362	422196.759	Unknown	Grand County	2536.779	2536.710	0.069	0.005
42	4376076.535	428443.961	Unknown	Grand County	3688.249	3688.340	-0.091	0.008
							sum	0.062
Outlier: a	a control point	located in an a	area that does	s not reflect			average	0.003

RMSE


NSSDA


0.056

0.109


Outlier: a control point located in an area that does not reflect the true ground elevation, i.e. bridges, etc.


CO_Grand_County Errors: Seamline Example 1







CO_Grand_County Errors: Seamline Example 2







CO_Grand_County Errors: Seamline Example 3






CO_Grand_County Errors: Water Not Leveled Area 1







CO_Grand_County Errors: Water Not Leveled Area 2






CO_Grand_County Errors: Unknown Error





CO_Grand_County Errors: Unknown Error Continued



FIRST ADDENDUM TO ORIGINAL REPORT FOR COLORADO GRAND COUNTY LIDAR CO_GrandCounty_2010

Data Corrections Received February 17th 2011. Reviewed on February 22nd 2011

This is the second time the data for Grand County, CO has been reviewed. This is the second QA report completed for the project. All of the original errors noted in the first QA report have been corrected. The water bodies have been leveled where necessary and the lidar elevation error points were corrected. In addition, this data has no seamlines. All apparent seamlines are a result of the hillshade algorithm in Global Mapper.

The errors reported in the initial reviewing of this data were concentrated to four cells. While the errors have been fixed, these four cells are in the wrong projection (UTM NAD 1983 Zone 15) according to the metadata provided. Reviewer attempted to reproject data unsuccessfully. The four cells are DEM 3_1704385; DEM 3_1854385; DEM 3_2004370; and DEM 3_2004445.

Once again, this is the second QC report completed for this project. The purpose of this QC report is to check that the original errors were corrected, and to call attention to the new errors in the data. The original QC report is included along with screenshots of this error on the external hard drive.


The data is in need of further corrections.

See JPEG examples low.


CONCLUSIONS: 1. 95 % of artifacts removed


2. 95 % of vegetation penetrated3. 98 % of buildings removed

CO Grand County Original Project Area




CO Grand County Returned Project Area with Corrections






CO Grand County Corrected Cells: Actual Location of Missing Cells



CO Grand County Corrected Cells in Wrong Location



FINAL ADDENDUM TO ORIGINAL REPORT FOR COLORADO GRAND COUNTY LIDAR CO GrandCounty 2010

Data Corrections Received February 28, 2011. Initial Review Conducted on March 7, 2011. Final Review on March 21, 2011


This is the final time the data for Grand County, Colorado will be reviewed. Original errors in .IMG shapefiles have been corrected. Projection errors in .img files have been corrected. Reviewer noticed on the final check that the tile shapefile was in the wrong projection (UTM NAD 1983 Zone 15). Reviewer requested new shapefile in UTM NAD 1983 Zone 13. New shapefile in correct projection was received on March 17, 2011.

Reviewer brought data into Global Mapper. Reviewer checked areas where original errors occurred. All errors were corrected. Review created shapefiles of areas where corrections were done. These have been included on the external hard drive in the Metadata folder.

This data is accepted.


Please see JPEG Examples below:

Original Project Area




CO Grand County Project Area 2


E	E E	€	E	E	€ 6	E	€	E	E	E	E	E	€	E	E	€	E	E
2000 m	20000 m	m 00008	35000 m	440000 m	45000 m	450000 m	455000 m	460000 m	465000 m	470000 m	475000 m	480000 m	485000 m	490000 m	495000 m	500000 m	505000 m	510000 m
	A LECT																	55000 m
FI	Till	4																
FAR N			The state of the s															50000 m
					Company of the Compan			=				tr s	0 0				44	45000 m
		P SI			0.5			-				5					44	/40000 m
1									-								44	35000 m
	Maria				yu.	在 2											44	30000 m
	()	755 GW			au.	S 5											44	25000 m
	-	13			an and	3 3											44	20000 m
82.52		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	** (44	15000 m
					92	2 2												10000 m
<u> </u>				-	-			-					s	P			44	05000 m
-				=	<u> </u>											-	44	00000 m
-					Sec.												43	95000 m
-																	43	90000 m
																	43	85000 m
																	43	80000 m
88 80														8			43	75000 m
87 \$		1																



CO Grand County Correction 2: Water Leveled



A. Original .img file: Water not leveled



B. Corrected .img file: Water leveled

CO Grand County Correction 3: Water Leveled




A. Original .img file: Water not leveled




B. Corrected .img file: Water leveled

CO Grand County Correction 4: Unknown Error Fixed



A. Original .img file: unknown error




B. Corrected .img file: Unknown error removed

CO Grand County Correction 5: Tile Layout Shapefile Projection Fixed



A. Original Layout Shapefile: UTM NAD 1983 Zone 15 projection



B. Original Layout Shapefile: UTM NAD 1983 Zone 13 projection