High Resolution Elevation QA Review Report

Project: Iowa_CSW_01-16_Lidar_2010 Contract ID:
Liaison: Bob Lernen Partner(s): Contractor: Sanborn Map Co. In
Data Delivery Date: 02/10/2009, 05,0: Date Data Reviewed: 12/21/2009 - 01
Reviewer: Rusty Grout / Eric Jaramil Total Square Miles Reviewed: 4572.8 sq. mi
Elevation Type: LIDAR Format: xyz Grid Spacing: 1 meter Tile size: 1000 x 1000
Projection: UTM Zone: 15 Datum: NAD83 Units: Meters
Licensing: Public Domain Metadata: Project Level Acquisition Date: 04/07/2007 thru
Materials Received:
Bare earth ASCII .xyz files
Las point cloud .xyz files Metadata
Shape files
·
Vertical Accuracy Test Performed: Yes Test Point Source: USGS RMSE: 0.208 meters
Vertical Accuracy Test Notes:

A vertical check was performed on Iowa CSW 01-16 bare earth data. See the Iowa Statewide Lidar Vertical Accuracy Report sent with the final .img data.

QA Review Summary:


All of Iowa CSW 01-16 one meter Lidar data was reviewed. This data was brought into Global Mapper as .xyz point files. Las point files were created from the .xyz files then gridded to 1 meter data for QA/QC. Errors found and fixed in Global Mapper were 2 elevation errors, (errors found and not fixed throughout this project are road offsets see example below). This 1 meter data has been regridded 1 meter .img files. This data is accepted and will be sent to archive.

See error JEPG examples and documents attached below.


Conclusions: 1.89% of artifacts removed


- 2. 90% of vegetation removed
- 3.95% of buildings removed

Iowa CSW 01-16




Iowa CSW 11 elevation error 1






Iowa CSW 11 elevation error 2



Iowa CSW 11 elevation error (Fixed)



Iowa CSW road offset (not fixed)

