


# **Data Validation Report**

### from the National Geospatial Technical Operations Center in Support of the 3D Elevation Program

### FL\_HurricaneMichael\_4\_2020

2021-12-16







## Based on this review, the delivered data is **EXPECTED TO MEET** 3D Elevation Program requirements.

### **Work Unit Summary Information**

Project Name: FL_HurricaneMichael_2020_D20	Project ID: 188518	
WU Name: FL_HurricaneMichael_4_2020	Work Unit ID: 217056	
Mechanism: GPSC	Lidar Base Spec: 2.1	
Quality Level: 1	P-Method: 7 - Linear-Mode Lidar	
Horizontal EPSG Code: 6441	Vertical EPSG Code: 6360 Geoid Model: GEOID 12B	
The National Map Help Desk Email: tnm_help@usgs.gov		

The U.S. Geological Survey evaluates absolute vertical accuracy of the lidar and lidar-derived bare earth digital elevation model (DEM) data at the project level. Data are produced to meet 9.8 cm absolute vertical accuracy at the 95-percent confidence level in non-vegetated, open terrain. To review vertical accuracy results, please see the project report

#### Breaklines

Based on this Review, the USGS-NGTOC **ACCEPTS** the Breaklines

Breaklines are visually reviewed in conjunction with the bare earth DEM for spatial and geometric accuracy. Breaklines are confirmed to be three dimensional (3D) features and that elevations are at or just below the immediately surrounding terrain. Single- and double-line drainages are reviewed to ensure downstream flow. The USGS recognizes that differences in collection methodology, resampling techniques, and other factors that are unique to proprietary production do occur, and these will result in minor horizontal and vertical differences between breaklines derived on the fly.

	-		
Error Type	Subtype	Quantity	

#### **Reporting Metadata**

Based on this Review, the USGS-NGTOC ACCEPTS the Reporting MetadataReports from the contractor, including calibration, collection, and processing methods, are reviewed for<br/>accurate information. For more information, please see the work units metadata.Error TypeSubtypeQuantity

#### FGDC XML Metadata

Based on this Review, the USGS-NGTOC ACCEPTS the FGDC XML MetadataCSGDM .xml metadata are parsed using the USGS Geospatial Metadata Validation Service and reviewed for<br/>accurate information. CSDGM is maintained by the Federal Geographic Data Committee (FGDC).Error TypeSubtypeQuantity

#### Spatial Metadata

Based on this Review, the USGS-NGTOC ACCEPTS the Spatial Metadata

Spatial metadata from the contractor, including raster and vector datasets, are evaluated together with pertinent deliverables for geometric fidelity and attribution accuracy. For more information, please see the work units metadata.

Error Type	Subtype	Quantity





#### Project Name: FL\_HurricaneMichael\_2020\_D20

Raster Metadata						
Based on this Review, the USGS-NGTOC ACCEPTS the Raster Metadata						
None						
Error Type	Subtype	Quantity				
DEM						
Based on this Review, the	USGS-NGTOC ACCEPTS the DEM					
cloud geometry, raster pro	cessing methodology, point classific	00 or larger viewing scale to validate point ation, and breaklines. Comprehensive review es. For additional information, please see this				

Quantity

Quantity

Subtype

Visual and statistical review is performed on classified .las files to validate adherence to contracted specifications. A comprehensive review is completed to ensure consistency and accuracy across all files, including the spatial reference system. Classification verification is limited to the minimum required by applicable Lidar Base Specification. Classifications beyond the minimum are not verified by USGS. LAS files are evaluated to ensure the public header block, point data records, and variable/extended variable length records are correctly populated. For additional information, please see the work units metadata folder.

Subtype

Based on this Review, the USGS-NGTOC ACCEPTS the Pointcloud

Science for a changing world

work units metadata folder.

Error Type

Pointcloud

Error Type

